

Westlake Independent, Inc.

31290 La Baya Drive #1
Westlake Village, CA, 91362, US

818-889-0377

westlakeindependent@westlakeindependent.com



WIHA Main Inspection

Customer:		License:	-
Vehicle:	2008 HONDA CR-V	VIN:	
Inspection date:	11/01/2016	Odometer:	109,526 miles
Repair Order:	62802	Technician:	Jose Delgado

**We have inspected
your vehicle with the
following results:**





Jose Delgado, Technician







**Craig Kirkendall, Service
Advisor**





Inspection Details

Needs Immediate Attention		
Road Test	Observation	Action
Check for Pull	Pulls Right	Perform Wheel Alignment
In Car	Observation	Action
Brake/Running Lights	Right Brake Light Out	
Cabin Filter (PICTURE)	Dirty <i>Image(s):</i>  <i>Click on image for original size</i>	Replace
Under Hood	Observation	Action
Engine Oil	Dark <i>Notes:</i> Car due for 105,000 miles service (flush trans fluid) + cabin filter + flush brake fluid + replace coolant + flush power steering fluid . + replace rear diff. Fluid <i>Image(s):</i>  <i>Click on image for original size</i>	





Needs Immediate Attention

Transmission Fluid	<p>Dark <i>Notes:</i> See Fluid Tray Photo <i>Image(s):</i></p>  <p><i>Click on image for original size</i></p>	Flush Transmission
Check Power Steering	<p>Dark <i>Notes:</i> See Fluid Tray Photo <i>Image(s):</i></p>  <p><i>Click on image for original size</i></p>	Flush System
Brake Fluid	<p>Low Dark <i>Notes:</i> See Fluid Tray Photo <i>Image(s):</i></p>  <p><i>Click on image for original size</i></p>	Flush Brake System
Drive Belts	<p>WORN <i>Image(s):</i></p>  <p><i>Click on image for original size</i></p>	Replace
Cooling Fans	<p>Other <i>Notes:</i> Main coolant fan motor inop</p>	




Needs Immediate Attention

Engine Air Filter (PICTURE)	Dirty <i>Image(s):</i>  <i>Click on image for original size</i>	Replace
Valve adjustment	Due By Mileage	Adjust valves
Tune Up, Spark Plug Condition	Spark Plugs Worn <i>Image(s):</i>  <i>Click on image for original size</i>	Replace
Under Car	Observation	Action
Right Front Tire	Cracking Rubber 3/32 Tread Left <i>Image(s):</i>   <i>Click on image for original size</i>	Replace Tires Alignment

Needs Immediate Attention

Left Front Tire	<p>Cracking Rubber 2/32 Tread Left <i>Image(s):</i></p>  <p><i>Click on image for original size</i></p>	<p>Replace Tires Alignment</p>
Right Rear Tire	<p>Cracking Rubber Uneven Wear 2/32 Tread Left <i>Image(s):</i></p>  <p><i>Click on image for original size</i></p>	<p>Replace Tire Alignment</p>
Left Rear Tire	<p>Cracking Rubber Worn on Edges 2/32 Tread Left <i>Image(s):</i></p>  <p><i>Click on image for original size</i></p>	<p>Replace Tire Alignment</p>
Front Strut/Shocks	<p>Other <i>Notes:</i> Front struts are soft + missing the dust boots <i>Image(s):</i></p>  <p><i>Click on image for original size</i></p>	<p>Replace</p>

Needs Immediate Attention

Rear Strut/Shock	<p>Leaking Level 5 <i>Notes:</i> Rear struts leaking <i>Image(s):</i></p>  <p><i>Click on image for original size</i></p>	Replace
Rear Differential Fluid	<p>Fluid Dirty <i>Image(s):</i></p>  <p><i>Click on image for original size</i></p>	Drain And Refill
Other	<p>See Notes <i>Notes:</i> Rt front fender liner has a hole <i>Image(s):</i></p>  <p><i>Click on image for original size</i></p>	



Needs Attention


Under Hood	Observation	Action
Coolant Hoses	Original	
Under Car	Observation	Action
Right Front Brake	3 mm <i>Notes:</i> Rotor 27.39 min 26.0	Replace Brakes Pads Machine Brake Rotors



Needs Attention

Left Front Brake	3 mm <i>Notes:</i> Rotor 27.39 min 26.0	Replace Brakes Pads Machine Brake Rotors
Right Rear Brake	7 mm	
Left Rear Brake	7 mm	

Good

Walk Around	Observation	Action
Dashboard (Photo) KOE OFF	Good, No Issues <i>Image(s):</i>  <i>Click on image for original size</i>	
Dashboard (Photo) KOE ON	Good, No Issues <i>Image(s):</i>  <i>Click on image for original size</i>	
Check Body (4 Corner Photos)	No Action Needed <i>Image(s):</i>  <i>Click on image for original size</i>	

Good		
Other	Not Applicable	
Road Test	Observation	Action
Engine Cranking	Good, No Issues	
Warning Lights	Good, No Issues	
Shifting	Good, No Issues	
Engine Performance	Good, No Issues	
Braking Performance	Good, No Issues	
Parking Brake	Good, No Issues	
Suspension & Handling	Good, No Issues	
Road Noises	Good, No Issues	
Other	Not Applicable	
In Car	Observation	Action
Horn	Good, No Issues	
Turn Signals/Hazards	Good, No Issues	
Check Washers/Wiper Blades /Inserts	Good, No Issues	
AC/Heater (Vent Temp./Compressor Cycle)	Good, No Issues 40 Degrees F. <i>Image(s):</i>  <i>Click on image for original size</i>	
Headlights	Good, No Issues	
Reverse Lights	Good, No Issues	
License Plate Lights	Good, No Issues	
Window Operation	Good, No Issues	

Good		
Other	Not Applicable	
Under Hood	Observation	Action
Engine Coolant	Good, No Issues <i>Notes:</i> See Fluid Tray Photo <i>Image(s):</i>  <i>Click on image for original size</i>	
Windshield Washer Fluid	Good, No Issues	
Battery (Picture of test on top of Battery)	Good, No Issues <i>Image(s):</i>  <i>Click on image for original size</i>	
Throttle Body	Good, No Issues	
Motor Mounts	Good, No Issues	
Timing Belt	Not Applicable	
Hood Shocks	Not Applicable	
Check For Fluid Leaks	Good, No Issues	
Other	Not Applicable	
Under Car	Observation	Action
Spare Tire	Good, No Issues	
Tire Pressure	Good, No Issues	
Brake Hydraulics	Good, No Issues	
Brake Calipers	Good, No Issues	

Good

Steering Components	Good, No Issues	
CV Axles / Driveshafts	Good, No Issues	
Exhaust System	Good, No Issues	
Check For Fluid Leaks	Good, No Issues	
Front Differential Fluid	Not Applicable	
Transfer Case Fluid	Not Applicable	
Rotate Tires	Good, No Issues	
Cooling System Leaks	Good, No Issues	
Front Suspension Bushings	Good, No Issues	
Rear Suspension Bushings	Good, No Issues	